


TYRONE 2 - TR2XXX

IP rated downlights

design Roberto Mantovani



I INFORMAZIONI SULLA SOSTITUIBILITÀ O NON SOSTITUIBILITÀ DELLA SORGENTE LUMINOSA

GB INFORMATION ON REPLACEABILITY OR NON-REPLACEABILITY OF LIGHT SOURCE



- I Sorgente luminosa non sostituibile.
La sorgente luminosa contenuta in questo apparecchio di illuminazione può essere sostituita esclusivamente dal costruttore.
- GB Non-replaceable light source.
The light source contained in this luminaire shall only be replaced by the manufacturer.

I GIUSTIFICAZIONE TECNICA CIRCA LA NON SOSTITUIBILITÀ DELLA SORGENTE LUMINOSA

La sorgente luminosa potrebbe essere contaminata e/o danneggiata durante la sostituzione a causa di particelle di sporco.
Il metodo di fissaggio della sorgente luminosa potrebbe influire sulla sua efficienza termica (dissipazione di calore).
A causa dei requisiti di protezione IP, l'alloggiamento dell'apparecchio è incollato per fornire una protezione efficace contro l'ingresso di acqua, umidità e corpi estranei.

GB TECHNICAL JUSTIFICATION ABOUT NON-REPLACEABILITY OF LIGHT SOURCE

The light source could be contaminated and/or damaged during replacement due to dirt particles.
The method of fixing the light source could impact its thermal efficiency (heat dissipation).
Due to IP protection requirements, the luminaire housing is glued to provide effective protection against the ingress of water, moisture and foreign bodies.